

Michael O. Leavitt Governor Ted Stewart Executive Director James W. Carter Division Director 1594 West North Temple, Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

September 26, 1997

TO:

Minerals File

FROM:

Tony Gallegos, Reclamation Engineer Ad

RE:

Site Inspection, Tom Clark, Daddy Dearest Mine, S/015/046, Emery County, Utah

Date of Inspection:

July 29, 1997

Time of Inspection:

1450

Conditions:

Partly cloudy, cool

Participants:

Tony Gallegos, DOGM

Purpose of Inspection:

To examine the site while in the area

For clarification purposes, the mine operations from the south to the north are: Bret Clark's site, then Bob Clark's site, and then Tom Clark's site. All three sites are immediately adjacent to each other and include surface disturbances and underground workings.

This site was visited after leaving the Brett Clark site with Mr. Jim Hewett. At the time of this inspection some of the contract miners were loading out ore into a semi truck. The contract miners have been hired to work the Tom Clark Mine and also Bret Clark's mine in a rotating fashion. One of the miners explained that they were moving the ore out of the mine into the pile to be loaded into the truck so they would have room to drill and blast some additional ore.

Additional equipment currently located on the surface at this site included: a generator, a fuel tank, a water tank, a jeep, a small contractor's trailer and some tool boxes. Near the ore stockpile were a semi-trailer, a flatbed truck, an air compressor and several smaller fuel tanks.

A sketch of the surface disturbance for this site was made before leaving the area. Additional photographs of this mine site and the adjacent operations were taken from the ridge on the other side of the canyon.

jb cc:

Tom Clark, Operator

Dean Nyffeler, BLM, Price Field Office

S015046.ins